

State of Alaska  
Department of Fish and Game  
Nomination for Waters  
Important to Anadromous Fish

1992  
Year of Revision

Anadromous Water Catalog Volume SE Region I

USGS Quad Craig C-3

Name of Waterway Thorne River Tributary

Anadromous Water Catalog Number of Waterway \_\_\_\_\_

102-70-10580-2026-3-008-4020

Change to ☒ Atlas

☐ Catalog

☐ Both

Addition ☒

Deletion ☐

Correction ☒

Name addition:

USGS name \_\_\_\_\_

Local name \_\_\_\_\_

ALASKA DEPT. OF  
FISH & GAME

OCT 30 1991

REGION II  
HABITAT DIVISION

For Office Use

Nomination # 92 089

Richard Reed 10/28/91  
Regional Supervisor Date

Ed Wein 2/20/92

FI 1/24/92  
Drafted Date

Species	Date(s) Observed	Spawning	Rearing	Migration
<u>Coho</u>			<input checked="" type="checkbox"/>	

Comments: Provide any clarifying information, including number of fish observed, location of fish survey data, etc.

Information from USF S fish specialist report concerning  
bridge/culvert replacement project

Attach a copy of a map showing location of mouth and upper points of each species, specific stream reaches identified for spawning or rearing, locations of barriers, such as falls. Attach a copy of the fish survey data, if available.

Name of Observer (please print) Vince Harkay

Date: 10/23/91 Signature: by Donald P. Cornelius

Address: ADFG P.O. Box 667


Petersburg AK 99833.

Signature of Area Biologist: Donald P. Cornelius



4018







3000330 Road

M.P. 1.10

- 2 (25) A 72" arch cmp, provides partial fish passage. Culvert outlet has scoured down to a 1' drop. Major coho stream. May be able to mitigate scouring by developing the outlet pool. Culvert should be pulled after logging has been completed on this road system.

reinstall  
7/18-8/15

3013 Road

M.P. 0.9

- 1/2 (4) A 36" cmp, provides partial fish passage. Culvert outlet has a 6" drop-off. Could develop a pool with boulder rip-rap.

3015 Road

M.P. 4.6

- 2 A 24" cmp, does not pass fish. Culvert outlet has a 1' drop-off. Inlet is crushed, and culvert is failing, washing out the road. Marginal fish stream, goes dry in the summer. Replace existing cmp with a new pipe, bedded to pass fish.

M.P. 4.75

- 1 (2) A 36" cmp, does not pass fish. Culvert outlet has a 1' drop-off. Coho rearing stream. Need to replace existing pipe with a 48" or 60" cmp, bedded to pass fish.

M.P. 5.9

- 2 A 36" cmp, provides partial fish passage. Culvert outlet has a 6" drop-off. Culvert has developed a major scour pool below the outlet. Could use a 60" cmp. Coho salmon stream.

3015200

M.P. 2.35

- (1) A 36" cmp, does not pass fish. Culvert outlet has a 10" drop-off. Coho salmon stream. Need to remove or replace culvert. This pipe was not properly bedded to pass fish.

3030 Road

M.P. 0.05

- 3 A 120" arch cmp, does not pass fish. Major stream, very steep gradient(8%+). Resident fish stream. May be able to mitigate with outlet pool development. Site probably needs a bridge or similar structure to maintain longterm fish passage.